

TERRAIN TAMER SAFARI SNORKELS – ARMAX – 2024.

MAKE	MODEL	YEAR	ENGINE	CAPACITY	FUEL	TRANS	PART NO.	COMMENT
FORD								
EVEREST	UN	7/2015-	P5AT	3.2L Turbo	Diesel	RH	SS984HP	
EVEREST		2019-	YN2S	2.0L Turbo	Diesel	RH	SS984HP	Facelift to Current Models
EVEREST	U704	5/2022-	YNWS	2.0L Turbo	Diesel	RH	SS987HPD	
RANGER	PX	8/2011-	P4AT	2.2L Turbo	Diesel	RH	SS982HP	
RANGER	PX	8/2011-	P5AT	3.2L Turbo	Diesel	RH	SS982HP	
RANGER	PX111	2019-	YN2S	2.0L Turbo	Diesel	RH	SS984HP	Facelift to Current Models
RANGER	P703	5/2022-	BF2S	3.0L V6 Turbo	Diesel	RH	SS987HPD	
RANGER	Raptor	7/2018-	YN2S	2.0L Turbo	Diesel	RH	SS986HP	
ISUZU								
D MAX	TFS40	7/2020-	4JJ3TCX	3.0L Turbo	Diesel	RH	SS177HP	
MU-X	UCR40	7/2021-	4JJ3TCX	3.0L Turbo	Diesel	RH	SS177HP	
MU-X	UCS40	7/2021-	4JJ3TCX	3.0L Turbo	Diesel	RH	SS177HP	
TOYOTA								
HILUX	GUN125	10/2015-	2GDFTV	2.4L Turbo	Diesel	RH	SS123HP	Wide Front 1855mm Workmate SR & SR5 Only
HILUX	GUN126	10/2015-	1GDFTV	2.8L Turbo	Diesel	RH	SS123HP	Wide Front 1855mm Workmate SR & SR5 Only
HILUX	KUN26	3/2005-6/2015	1KDFTV	3.0L Turbo	Diesel	RH	SS122HP	
LANDCRUISER	FJA300	7/2021-	F33AFTV	3.3L	Diesel	LH	SS98HP	SS98HPOER required for models with OE Raised Air Intake
								SS98HPOER required for GX models
LANDCRUISER	FZJ105	1/1998-	1FZFE	4.5L	Petrol	RH	SS86HP	Right Hand Drive Only will Not Suit Japanese Imports
LANDCRUISER	GDJ76	9/2023-	1GDFTV	2.8L Turbo	Diesel	RH	SS792HPGD	Replacement for Genuine Snorkel
LANDCRUISER	GDJ78	9/2023-	1GDFTV	2.8L Turbo	Diesel	RH	SS792HPGD	Replacement for Genuine Snorkel
LANDCRUISER	GDJ79	9/2023-	1GDFTV	2.8L Turbo	Diesel	RH	SS792HPGD	Replacement for Genuine Snorkel
LANDCRUISER	HDJ78	8/1999-2007	1HDFTE	4.2L Turbo	Diesel	RH	SS70HP	Replacement for Genuine Snorkel
LANDCRUISER	HDJ79	8/1999-2007	1HDFTE	4.2L Turbo	Diesel	RH	SS70HP	Replacement for Genuine Snorkel
LANDCRUISER	HDJ100	1/1998-	1HDFTE	4.2L Turbo	Diesel	RH	SS86HP	Right Hand Drive Only will Not Suit Japanese Imports
LANDCRUISER	HZJ71	1/1990-	1HZ	4.2L	Diesel	RH	SS70HP	Replacement for Genuine Snorkel
LANDCRUISER	HZJ73	1/1990-	1HZ	4.2L	Diesel	RH	SS70HP	Replacement for Genuine Snorkel
LANDCRUISER	HZJ75	1/1990-	1HZ	4.2L	Diesel	RH	SS70HP	Replacement for Genuine Snorkel
LANDCRUISER	HZJ78	8/1999-2007	1HZ	4.2L	Diesel	RH	SS70HP	Replacement for Genuine Snorkel
LANDCRUISER	HZJ79	8/1999-2007	1HZ	4.2L	Diesel	RH	SS70HP	Replacement for Genuine Snorkel
LANDCRUISER	HZJ105	1/1998-	1HZ	4.2L	Diesel	RH	SS86HP	Right Hand Drive Only will Not Suit Japanese Imports
LANDCRUISER	UZJ100	1/1998-	2UZFE	4.7L	Petrol	RH	SS86HP	Right Hand Drive Only will Not Suit Japanese Imports
LANDCRUISER	URJ202	3/2012-8/2015	1URFE	4.6L	Petrol	RH	SS88HP	Requires SS88HPOER for Vehicles with OE Raised Air Intake Snorkel
LANDCRUISER	URJ202	9/2015-3/2021	1URFE	4.6L	Petrol	RH	SS89HP	Requires SS89HPOER for Vehicles with OE Raised Air Intake Snorkel
LANDCRUISER	UZJ200	11/2007-2/2012	2UZFE	4.7L	Petrol	RH	SS88HP	Requires SS88HPOER for Vehicles with OE Raised Air Intake Snorkel
LANDCRUISER	VDJ76	1/2007-8/2023	1VDTFV	4.5L Turbo	Diesel	RH	SS79HPV	Replacement for Genuine Snorkel
LANDCRUISER	VDJ76	9/2023-	1VDTFV	4.5L Turbo	Diesel	RH	SS792HPVD	Replacement for Genuine Snorkel
LANDCRUISER	VDJ78	1/2007-8/2023	1VDTFV	4.5L Turbo	Diesel	RH	SS79HPV	Replacement for Genuine Snorkel
LANDCRUISER	VDJ78	9/2023-	1VDTFV	4.5L Turbo	Diesel	RH	SS792HPVD	Replacement for Genuine Snorkel
LANDCRUISER	VDJ79	1/2007-8/2023	1VDTFV	4.5L Turbo	Diesel	RH	SS79HPV	Replacement for Genuine Snorkel
LANDCRUISER	VDJ79	9/2023-	1VDTFV	4.5L Turbo	Diesel	RH	SS792HPVD	Replacement for Genuine Snorkel
LANDCRUISER	VDJ200	7/2007-8/2015	1VDTFV	4.5L Turbo	Diesel	RH	SS88HP	Requires SS88HPOER for Vehicles with OE Raised Air Intake Snorkel
LANDCRUISER	VDJ200	9/2015-3/2021	1VDTFV	4.5L Turbo	Diesel	RH	SS89HP	Requires SS89HPOER for Vehicles with OE Raised Air Intake Snorkel
LEXUS	LX470	1/1998-	2UZFE	4.7L	Petrol	RH	SS86HP	Right Hand Drive Only will Not Suit Japanese Imports
VOLKSWAGEN								
AMAROK		9/2016-	TDI550	3.0L V6	Diesel	RH	SS1410HP	

