

TERRAIN TAMER ASSEMBLED DOORS – 2026.

MAKE	MODEL	YEAR	PART NO.	APPLICATION
TOYOTA				
LANDCRUISER	FZJ78	8/1999-	67001-60490C	R/H with 1/4 Window
LANDCRUISER	FZJ78	8/1999-	67002-60490C	L/H with 1/4 Window
LANDCRUISER	FZJ78	8/1999-	67001-60490CFG	R/H without 1/4 Window
LANDCRUISER	FZJ78	8/1999-	67002-60490CFG	L/H without 1/4 Window
LANDCRUISER	FZJ78	8/1999-	67001-60650C/MS	R/H with 1/4 Window Mine Spec.
LANDCRUISER	FZJ78	8/1999-	67002-60650C/MS	L/H with 1/4 Window Mine Spec.
LANDCRUISER	FZJ79	8/1999-	67001-60490C	R/H with 1/4 Window
LANDCRUISER	FZJ79	8/1999-	67002-60490C	L/H with 1/4 Window
LANDCRUISER	FZJ79	8/1999-	67001-60490CFG	R/H without 1/4 Window
LANDCRUISER	FZJ79	8/1999-	67002-60490CFG	L/H without 1/4 Window
LANDCRUISER	FZJ79	8/1999-	67001-60650C/MS	R/H with 1/4 Window Mine Spec.
LANDCRUISER	FZJ79	8/1999-	67002-60650C/MS	L/H with 1/4 Window Mine Spec.
LANDCRUISER	GRJ79	8/2016-	67002-60800C/MS	L/H Front Dual Cab Mine Spec. PNG & Import Vehicles
LANDCRUISER	HDJ78	8/2001-	67001-60490C	R/H with 1/4 Window
LANDCRUISER	HDJ78	8/2001-	67002-60490C	L/H with 1/4 Window
LANDCRUISER	HDJ78	8/2001-	67001-60490CFG	R/H without 1/4 Window
LANDCRUISER	HDJ78	8/2001-	67002-60490CFG	L/H without 1/4 Window
LANDCRUISER	HDJ78	8/2001-	67001-60650C/MS	R/H with 1/4 Window Mine Spec.
LANDCRUISER	HDJ78	8/2001-	67002-60650C/MS	L/H with 1/4 Window Mine Spec.
LANDCRUISER	HDJ79	8/2001-	67001-60490C	R/H with 1/4 Window
LANDCRUISER	HDJ79	8/2001-	67002-60490C	L/H with 1/4 Window
LANDCRUISER	HDJ79	8/2001-	67001-60490CFG	R/H without 1/4 Window
LANDCRUISER	HDJ79	8/2001-	67002-60490CFG	L/H without 1/4 Window
LANDCRUISER	HDJ79	8/2001-	67001-60650C/MS	R/H with 1/4 Window Mine Spec.
LANDCRUISER	HDJ79	8/2001-	67002-60650C/MS	L/H with 1/4 Window Mine Spec.
LANDCRUISER	HZJ78	8/1999-	67001-60490C	R/H with 1/4 Window
LANDCRUISER	HZJ78	8/1999-	67002-60490C	L/H with 1/4 Window
LANDCRUISER	HZJ78	8/1999-	67001-60490CFG	R/H without 1/4 Window
LANDCRUISER	HZJ78	8/1999-	67002-60490CFG	L/H without 1/4 Window
LANDCRUISER	HZJ78	8/1999-	67001-60650C/MS	R/H with 1/4 Window Mine Spec.
LANDCRUISER	HZJ78	8/1999-	67002-60650C/MS	L/H with 1/4 Window Mine Spec.
LANDCRUISER	HZJ79	8/1999-	67001-60490C	R/H with 1/4 Window Single Cab
LANDCRUISER	HZJ79	8/1999-	67002-60490C	L/H with 1/4 Window Single Cab
LANDCRUISER	HZJ79	8/1999-	67001-60490CFG	R/H without 1/4 Window Single Cab
LANDCRUISER	HZJ79	8/1999-	67002-60490CFG	L/H without 1/4 Window Single Cab
LANDCRUISER	HZJ79	8/1999-	67001-60650C/MS	R/H with 1/4 Window Mine Spec.
LANDCRUISER	HZJ79	8/1999-	67002-60650C/MS	L/H with 1/4 Window Mine Spec.
LANDCRUISER	HZJ79	8/2016-	67002-60800C/MS	L/H Front Dual Cab Mine Spec. PNG & Import Vehicles
LANDCRUISER	VDJ79	1/2007-	67001-60490C	R/H with 1/4 Window Single Cab
LANDCRUISER	VDJ79	1/2007-2018	67002-60490C	L/H with 1/4 Window Single Cab
LANDCRUISER	VDJ79	1/2007-	67001-60490CFG	R/H without 1/4 Window Single Cab
LANDCRUISER	VDJ79	1/2007-	67002-60490CFG	L/H without 1/4 Window Single Cab
LANDCRUISER	VDJ79	1/2007-	67001-60650C/MS	R/H with 1/4 Window Mine Spec.
LANDCRUISER	VDJ79	1/2007-	67002-60650C/MS	L/H with 1/4 Window Mine Spec.
LANDCRUISER	VDJ79	8/2012-7/2016	67001-60820C	R/H Front Dual Cab
LANDCRUISER	VDJ79	8/2012-7/2016	67002-60820C	L/H Front Dual Cab
LANDCRUISER	VDJ79	8/2012-	67003-60051C	R/H Rear Dual Cab
LANDCRUISER	VDJ79	8/2012-	67003-60051C/MS	R/H Rear Dual Cab Mine Spec.
LANDCRUISER	VDJ79	8/2012-	67004-60051C	L/H Rear Dual Cab
LANDCRUISER	VDJ79	8/2012-	67004-60051C/MS	L/H Rear Dual Cab Mine Spec.
LANDCRUISER	VDJ79	1/2017-	67002-60800C/MS	L/H Front Dual Cab Mine Spec. PNG & Import Vehicles

