

TERRAIN TAMER CV JOINTS – 2022.

MAKE	MODEL	YEAR	ENGINE	PART NO.	NOTES
FORD					
RANGER	PX	9/2011-	P4AT/P5AT Diesel	UF9T2560X	CV Joint & Axle Shaft Assembly L/H
RANGER	PX	9/2011-	P4AT/P5AT Diesel	UF9T2550X	CV Joint & Axle Shaft Assembly R/H
MAZDA					
BT50	UP/UR	9/2011-7/2020	P4AT/P5AT Diesel	UF9T2560X	CV Joint & Axle Shaft Assembly L/H
BT50	UP/UR	9/2011-7/2020	P4AT/P5AT Diesel	UF9T2550X	CV Joint & Axle Shaft Assembly R/H
mitsubishi					
TRITON	ML	3/2006-8/2009	6G74 Petrol	3815A309	CV Joint & Axle Shaft Assembly with ABS L/H
TRITON	ML	3/2006-8/2009	6G74 Petrol	3815A310	CV Joint & Axle Shaft Assembly with ABS R/H
TRITON	ML	3/2006-8/2009	4M41T Diesel	3815A309	CV Joint & Axle Shaft Assembly with ABS L/H
TRITON	ML	3/2006-8/2009	4M41T Diesel	3815A310	CV Joint & Axle Shaft Assembly with ABS R/H
TRITON	ML	3/2006-8/2009	4D56T Diesel	3815A309	CV Joint & Axle Shaft Assembly with ABS L/H
TRITON	ML	3/2006-8/2009	4D56T Diesel	3815A310	CV Joint & Axle Shaft Assembly with ABS R/H
TRITON	MN	10/2009-4/2015	4D56T Diesel	3815A309	CV Joint & Axle Shaft Assembly with ABS L/H
TRITON	MN	10/2009-4/2015	4D56T Diesel	3815A310	CV Joint & Axle Shaft Assembly with ABS R/H
TRITON	MQ	5/2015-	4N15 Diesel	3815A309	CV Joint & Axle Shaft Assembly with ABS L/H
TRITON	MQ	5/2015-	4N15 Diesel	3815A310	CV Joint & Axle Shaft Assembly with ABS R/H
NISSAN					
PATROL	GQ	8/1987-	RB30S Petrol	39100-MS12A30J	CV Joint L/H or R/H
PATROL	GQ	9/1988-	RB30S Petrol	39101-01J10	CV Joint & Axle Shaft Assembly Coil Spring L/H
PATROL	GQ	9/1988-	RD28T Diesel	39101-01J10	CV Joint & Axle Shaft Assembly Coil Spring L/H
PATROL	GQ	8/1987-	TB42E Petrol	39100-MS12A30J	CV Joint L/H & R/H
PATROL	GQ	9/1988-	TB42E Petrol	39101-01J10	CV Joint & Axle Shaft Assembly Coil Spring L/H
PATROL	GQ	8/1987-	TB42S Petrol	39100-MS12A30J	CV Joint L/H & R/H
PATROL	GQ	8/1987-	TB42S Petrol	39101-01J10	CV Joint & Axle Shaft Assembly Coil Spring L/H
PATROL	GQ	8/1987-	TB42S Petrol	39101-10J10	CV Joint & Axle Shaft Assembly Leaf Spring L/H
PATROL	GQ	8/1987-	TB42S Petrol	39100-10J10	CV Joint & Axle Shaft Assembly R/H
PATROL	GQ	8/1987-	TD42 Diesel	39100-MS12A30J	CV Joint L/H & R/H
PATROL	GQ	8/1987-	TD42 Diesel	39101-01J10	CV Joint & Axle Shaft Assembly Coil Spring L/H
PATROL	GQ	8/1987-	TD42 Diesel	39101-10J10	CV Joint & Axle Shaft Assembly Leaf Spring L/H
PATROL	GQ	8/1987-	TD42 Diesel	39100-10J10	CV Joint & Axle Shaft Assembly R/H
PATROL	GU	11/1997-	RD28T Diesel	39100-86N454	CV Joint L/H & R/H
PATROL	GU	11/1997-	RD28T Diesel	39101-VB001	CV Joint & Axle Shaft Assembly L/H
PATROL	GU	11/1997-	RD28T Diesel	39100-VB001	CV Joint & Axle Shaft Assembly R/H
PATROL	GU	11/1997-	TB45E Petrol	39100-86N454	CV Joint L/H & R/H
PATROL	GU	11/1997-	TB45E Petrol	39101-VB001	CV Joint & Axle Shaft Assembly L/H
PATROL	GU	11/1997-	TB45E Petrol	39100-VB001	CV Joint & Axle Shaft Assembly R/H
PATROL	GU	11/1997-	TB48E Petrol	39100-86N454	CV Joint L/H & R/H
PATROL	GU	11/1997-	TB48E Petrol	39101-VB001	CV Joint & Axle Shaft Assembly L/H
PATROL	GU	11/1997-	TB48E Petrol	39100-VB001	CV Joint & Axle Shaft Assembly R/H
PATROL	GU	11/1997-	TD42 Diesel	39100-86N454	CV Joint L/H & R/H
PATROL	GU	11/1997-	TD42 Diesel	39101-VB001	CV Joint & Axle Shaft Assembly L/H
PATROL	GU	11/1997-	TD42 Diesel	39100-VB001	CV Joint & Axle Shaft Assembly R/H
PATROL	GU	11/1997-	ZD30DDTI Diesel	39100-86N454	CV Joint L/H & R/H
PATROL	GU	11/1997-	ZD30DDTI Diesel	39101-VB001	CV Joint & Axle Shaft Assembly L/H
PATROL	GU	11/1997-	ZD30DDTI Diesel	39100-VB001	CV Joint & Axle Shaft Assembly R/H
TOYOTA					
FJ CRUISER	GSJ15	11/2010-	1GRFE Petrol	43430-60060TT	CV Joint & Drive Shaft Assembly L/H & R/H
FORTUNER	GUN156	7/2015-	1GDFTV Diesel	43430-0K070TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	GGN25	8/2004-	1GRFE Petrol	43430-0K022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	GGN125	5/2015-	1GRFE Petrol	43430-0K070TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	GUN125	5/2015-	2GDFTV Diesel	43430-0K070TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	GUN126	5/2015-	1GDFTV Diesel	43430-0K070TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	KDN165	8/2001-	2KDFTV Diesel	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	KDN165	8/2001-9/2003	2KDFTV Diesel	43430-35022TT	CV Joint Outer & Drive Shaft Assembly L/H & R/H
HILUX	KDN165	8/2001-	2KDFTV Diesel	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	KUN25	7/2005-	2KDFTV Diesel	43430-0K022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	KUN26	8/2004-	1KDFTV Diesel	43430-0K022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	KUN125	5/2015-	2KDFTV Diesel	43430-0K070TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	KUN126	5/2015-	1KDFTV Diesel	43430-0K070TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	KZN165	8/1997-	1KZTE Diesel	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	KZN165	8/1997-9/2003	1KZTE Diesel	43430-35022TT	CV Joint Outer & Drive Shaft Assembly L/H & R/H
HILUX	KZN165	8/1997-	1KZTE Diesel	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	KZN185	11/1995-	1KZTE Diesel	43430-35030TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	LN46	1/1979-7/1983	L Diesel	43405-60015TT	CV Joint L/H & R/H
HILUX	LN46	1/1979-7/1983	L Diesel	43412-35010CV	CV Joint & Axle Assembly L/H
HILUX	LN46	1/1979-7/1983	L Diesel	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	LN60	8/1983-	2L Diesel	43405-60015TT	CV Joint L/H & R/H
HILUX	LN60	8/1983-	2L Diesel	43412-35010CV	CV Joint & Axle Assembly L/H
HILUX	LN60	8/1983-	2L Diesel	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	LN65	8/1983-	2L Diesel	43405-60015TT	CV Joint L/H & R/H
HILUX	LN65	8/1983-	2L Diesel	43412-35010CV	CV Joint & Axle Assembly L/H

TERRAIN TAMER CV JOINTS – 2022.

MAKE	MODEL	YEAR	ENGINE	PART NO.	NOTES
HILUX	LN65	8/1983-	2L Diesel	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	LN106	8/1988-	3L Diesel	43405-60015TT	CV Joint L/H & R/H
HILUX	LN106	8/1988-	3L Diesel	43412-35010CV	CV Joint & Axle Assembly L/H
HILUX	LN106	8/1988-	3L Diesel	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	LN107	8/1988-	3L Diesel	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	LN107	8/1988-	3L Diesel	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	LN111	8/1988-	3L Diesel	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	LN111	8/1988-	3L Diesel	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	LN130	8/1988-	3L Diesel	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	LN130	8/1988-	3L Diesel	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	LN167	8/1997-	5L Diesel	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	LN167	8/1997-9/2003	5L Diesel	43430-35022TT	CV Joint Outer & Drive Shaft Assembly L/H & R/H
HILUX	LN167	8/1997-	5L Diesel	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	LN172	8/1997-	5L Diesel	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	LN172	8/1997-9/2003	5L Diesel	43430-35022TT	CV Joint Outer & Drive Shaft Assembly L/H & R/H
HILUX	LN172	8/1997-	5L Diesel	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	RN36	1/1979-7/1983	18R Petrol	43405-60015TT	CV Joint L/H & R/H
HILUX	RN36	1/1979-7/1983	18R Petrol	43412-35010CV	CV Joint & Axle Assembly L/H
HILUX	RN36	1/1979-7/1983	18R Petrol	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	RN46	1/1979-7/1983	18R Petrol	43405-60015TT	CV Joint L/H & R/H
HILUX	RN46	1/1979-7/1983	18R Petrol	43412-35010CV	CV Joint & Axle Assembly L/H
HILUX	RN46	1/1979-7/1983	18R Petrol	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	RN105	8/1988-	22R Petrol	43405-60015TT	CV Joint L/H & R/H
HILUX	RN105	8/1988-	22R Petrol	43412-35010CV	CV Joint & Axle Assembly L/H
HILUX	RN105	8/1988-	22R Petrol	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	RN106	6/1989-	22R Petrol	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	RN106	8/1988-	22R Petrol	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	RN110	6/1989-	22R Petrol	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	RN110	8/1988-	22R Petrol	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	RN130	6/1989-	22R Petrol	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	RN130	6/1989-	22R Petrol	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	RZN169	8/1997-	3RZFE Petrol	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	RZN169	8/1997-9/2003	3RZFE Petrol	43430-35022TT	CV Joint Outer & Drive Shaft Assembly L/H & R/H
HILUX	RZN169	8/1997-	3RZFE Petrol	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	RZN174	8/1997-	3RZFE Petrol	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	RZN174	8/1997-9/2003	3RZFE Petrol	43430-35022TT	CV Joint Outer & Drive Shaft Assembly L/H & R/H
HILUX	RZN174	8/1997-	3RZFE Petrol	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	RZN185	8/2000-	3RZFE Petrol	43430-35030TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	TGN126	5/2015-	2TRFE Petrol	43430-0K070TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	VZN130	6/1989-	3VZE Petrol	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	VZN130	6/1989-	3VZE Petrol	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	VZN167	8/2001-	5VZFE Petrol	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	VZN167	8/2001-9/2003	5VZFE Petrol	43430-35022TT	CV Joint Outer & Drive Shaft Assembly L/H & R/H
HILUX	VZN167	8/2001-	5VZFE Petrol	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	VZN172	8/2001-	5VZFE Petrol	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	VZN172	8/2001-9/2003	5VZFE Petrol	43430-35022TT	CV Joint Outer & Drive Shaft Assembly L/H & R/H
HILUX	VZN172	8/2001-	5VZFE Petrol	43403-35020TT	CV Joint Inner L/H & R/H
HILUX	VZN185	7/1998-	5VZFE Petrol	43430-35030TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	YN60	8/1983-	3Y Petrol	43405-60015TT	CV Joint L/H & R/H
HILUX	YN60	8/1983-	3Y Petrol	43412-35010CV	CV Joint & Axle Assembly L/H
HILUX	YN60	8/1983-	3Y Petrol	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	YN65	8/1983-	3Y Petrol	43405-60015TT	CV Joint L/H & R/H
HILUX	YN65	8/1983-	3Y Petrol	43412-35010CV	CV Joint & Axle Assembly L/H
HILUX	YN65	8/1983-	3Y Petrol	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	YN67	8/1983-	3Y Petrol	43405-60015TT	CV Joint L/H & R/H
HILUX	YN67	8/1983-	3Y Petrol	43412-35010CV	CV Joint & Axle Assembly L/H
HILUX	YN67	8/1983-	3Y Petrol	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	YN106	8/1988-	4Y Petrol	43405-60015TT	CV Joint L/H & R/H
HILUX	YN106	8/1988-	4Y Petrol	43412-35010CV	CV Joint & Axle Assembly L/H
HILUX	YN106	8/1988-	4Y Petrol	43411-35010CV	CV Joint & Axle Assembly R/H
HILUX	YN130	6/1989-	4Y Petrol	43430-35022TT	CV Joint & Drive Shaft Assembly L/H & R/H
HILUX	YN130	6/1989-	4Y Petrol	43403-35020TT	CV Joint Inner L/H & R/H
LANDCRUISER	BJ40	1/1979-10/1984	B Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	BJ40	1/1979-10/1984	B Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	BJ40	1/1979-10/1984	B Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	BJ42	1/1979-10/1984	3B Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	BJ42	8/1980-	3B Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	BJ42	8/1980-10/1984	3B Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	BJ45	8/1980-	3B Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	BJ45	8/1980-	3B Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	BJ45	8/1980-	3B Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	BJ46	8/1980-	3B Diesel	43405-60015TT	CV Joint L/H & R/H

TERRAIN TAMER CV JOINTS – 2022.

MAKE	MODEL	YEAR	ENGINE	PART NO.	NOTES
LANDCRUISER	BJ46	8/1980-	3B Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	BJ46	8/1980-	3B Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	BJ60	8/1980-	3B Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	BJ60	8/1980-	3B Diesel	43412-35010CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	BJ60	8/1980-	3B Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly without Diff Lock R/H
LANDCRUISER	BJ70	11/1984-	3B Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	BJ70	11/1984-	3B Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly without Diff Lock L/H
LANDCRUISER	BJ70	11/1984-	3B Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly without Diff Lock R/H
LANDCRUISER	BJ73	11/1984-	3B Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	BJ73	11/1984-	3B Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly without Diff Lock L/H
LANDCRUISER	BJ73	11/1984-	3B Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly without Diff Lock R/H
LANDCRUISER	BJ74	11/1984-1/1990	13BT Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	BJ74	1/1990-	13BT Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	BJ74	11/1984-1/1990	13BT Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly without Diff Lock L/H
LANDCRUISER	BJ74	11/1984-1/1990	13BT Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly without Diff Lock R/H
LANDCRUISER	BJ75	11/1984-8/1988	3B Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	BJ75	11/1984-8/1988	3B Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly without Diff Lock L/H
LANDCRUISER	BJ75	11/1984-8/1988	3B Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly without Diff Lock R/H
LANDCRUISER	FJ40	1/1979-10/1984	2F Petrol	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	FJ40	1/1979-10/1984	2F Petrol	43412-60090CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FJ40	1/1979-10/1984	2F Petrol	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FJ45	1/1979-10/1984	2F Petrol	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	FJ45	1/1979-10/1984	2F Petrol	43412-60090CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FJ45	1/1979-10/1984	2F Petrol	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FJ55	1/1979-7/1980	2F Petrol	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	FJ55	1/1979-7/1980	2F Petrol	43412-60090CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FJ55	1/1979-7/1980	2F Petrol	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FJ60	8/1980-1/1990	2F Petrol	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	FJ60	8/1980-1/1990	2F Petrol	43412-35010CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FJ60	8/1980-1/1990	2F Petrol	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FJ62	8/1980-1/1990	3F Petrol	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	FJ62	8/1980-1/1990	3F Petrol	43412-35010CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FJ62	8/1980-1/1990	3F Petrol	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FJ70	11/1984-1/1990	3F Petrol	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	FJ70	11/1984-1/1990	3F Petrol	43412-60090CV	CV Joint & Axle Shaft Assembly without Diff Lock L/H
LANDCRUISER	FJ70	11/1984-1/1990	3F Petrol	43411-60060CV	CV Joint & Axle Shaft Assembly without Diff Lock R/H
LANDCRUISER	FJ70	1/1990-	3F Petrol	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	FJ70	1/1990-	3F Petrol	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FJ70	1/1990-	3F Petrol	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FJ73	11/1984-1/1990	3F Petrol	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	FJ73	11/1984-1/1990	3F Petrol	43412-60090CV	CV Joint & Axle Shaft Assembly without Diff Lock L/H
LANDCRUISER	FJ73	11/1984-1/1990	3F Petrol	43411-60060CV	CV Joint & Axle Shaft Assembly without Diff Lock R/H
LANDCRUISER	FJ73	1/1990-	3F Petrol	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	FJ73	1/1990-	3F Petrol	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FJ73	1/1990-	3F Petrol	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FJ75	11/1984-1/1990	3F Petrol	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	FJ75	11/1984-1/1990	3F Petrol	43412-60090CV	CV Joint & Axle Shaft Assembly without Diff Lock L/H
LANDCRUISER	FJ75	11/1984-1/1990	3F Petrol	43411-60060CV	CV Joint & Axle Shaft Assembly without Diff Lock R/H
LANDCRUISER	FJ75	1/1990-	3F Petrol	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	FJ75	1/1990-	3F Petrol	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FJ75	1/1990-	3F Petrol	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FJ80	1/1990-8/1992	3F Petrol	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FJ80	1/1990-8/1992	3F Petrol	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	FJ80	1/1990-8/1992	3F Petrol	43412-60110FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub Type L/H
LANDCRUISER	FJ80	1/1990-8/1992	3F Petrol	43411-60090FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub Type R/H
LANDCRUISER	FZJ70	1/1990-	1FZFE Petrol	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	FZJ70	1/1990-	1FZFE Petrol	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FZJ70	1/1990-	1FZFE Petrol	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FZJ73	1/1990-	1FZFE Petrol	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	FZJ73	1/1990-	1FZFE Petrol	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FZJ73	1/1990-	1FZFE Petrol	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FZJ75	1/1990-	1FZFE Petrol	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	FZJ75	1/1990-	1FZFE Petrol	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	FZJ75	1/1990-	1FZFE Petrol	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	FZJ76	1/2007-	1FZFE Petrol	43405-60100TT	CV Joint non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FZJ76	1/2007-	1FZFE Petrol	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FZJ76	1/2007-	1FZFE Petrol	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	FZJ76	1/2007-	1FZFE Petrol	43412-60140CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type L/H
LANDCRUISER	FZJ76	1/2007-	1FZFE Petrol	43412-60140TTCVG	CV Joint & Axle Shaft Assembly with Grease Valve Auto & Free Wheeling Hub Type L/H
LANDCRUISER	FZJ76	1/2007-	1FZFE Petrol	43412-60120NFHCV	CV Joint & Axle Shaft non Free Wheeling Hub Type L/H
LANDCRUISER	FZJ76	1/2007-	1FZFE Petrol	43411-60100CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type R/H
LANDCRUISER	FZJ76	8/1999-8/2016	1FZFE Petrol	43411-60100CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type R/H

TERRAIN TAMER CV JOINTS – 2022.

MAKE	MODEL	YEAR	ENGINE	PART NO.	NOTES
LANDCRUISER	FZJ76	1/2007-	1FZFE Petrol	43411-60100NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub Type R/H
LANDCRUISER	FZJ78	8/1999-	1FZFE Petrol	43405-60100TT	CV Joint non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FZJ78	8/1999-	1FZFE Petrol	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FZJ78	8/1999-	1FZFE Petrol	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	FZJ78	8/1999-1/2007	1FZFE Petrol	43412-60120CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type L/H
LANDCRUISER	FZJ78	8/1999-1/2007	1FZFE Petrol	43412-60120CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type L/H
LANDCRUISER	FZJ78	8/1999-1/2007	1FZFE Petrol	43412-60120NFHCV	CV Joint & Axle Shaft non Free Wheeling Hub Type L/H
LANDCRUISER	FZJ78	1/2007-	1FZFE Petrol	43412-60140TTCVG	CV Joint & Axle Shaft Assembly with Grease Valve Auto & Free Wheeling Hub Type L/H
LANDCRUISER	FZJ78	8/1999-	1FZFE Petrol	43411-60100CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type R/H
LANDCRUISER	FZJ78	8/1999-8/2016	1FZFE Petrol	43411-60100CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type R/H
LANDCRUISER	FZJ78	8/1999-	1FZFE Petrol	43411-60100NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub Type R/H
LANDCRUISER	FZJ79	8/1999-	1FZFE Petrol	43405-60100TT	CV Joint non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FZJ79	8/1999-	1FZFE Petrol	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FZJ79	8/1999-	1FZFE Petrol	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	FZJ79	8/1999-1/2007	1FZFE Petrol	43412-60120CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type L/H
LANDCRUISER	FZJ79	8/1999-1/2007	1FZFE Petrol	43412-60120CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type L/H
LANDCRUISER	FZJ79	8/1999-1/2007	1FZFE Petrol	43412-60120NFHCV	CV Joint & Axle Shaft non Free Wheeling Hub Type L/H
LANDCRUISER	FZJ79	1/2007-	1FZFE Petrol	43412-60140TTCVG	CV Joint & Axle Shaft Assembly with Grease Valve Auto & Free Wheeling Hub Type L/H
LANDCRUISER	FZJ79	8/1999-	1FZFE Petrol	43411-60100CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type R/H
LANDCRUISER	FZJ79	8/1999-8/2016	1FZFE Petrol	43411-60100CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type R/H
LANDCRUISER	FZJ79	8/1999-	1FZFE Petrol	43411-60100NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub Type R/H
LANDCRUISER	FZJ80	8/1992-	1FZFE Petrol	43405-60070TT	CV Joint with ABS L/H & R/H
LANDCRUISER	FZJ80	4/1994-	1FZFE Petrol	43405-60080TT	CV Joint without ABS L/H & R/H
LANDCRUISER	FZJ80	1/1990-	1FZFE Petrol	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FZJ80	1/1990-	1FZFE Petrol	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	FZJ80	8/1992-	1FZFE Petrol	43412-60110ABSCV	CV Joint & Axle Shaft Assembly with ABS L/H
LANDCRUISER	FZJ80	1/1990-	1FZFE Petrol	43412-60110FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub & Full Time 4wd L/H
LANDCRUISER	FZJ80	4/1994-	1FZFE Petrol	43412-60110NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub & ABS L/H
LANDCRUISER	FZJ80	8/1992-	1FZFE Petrol	43411-60090ABSCV	CV Joint & Axle Shaft Assembly with ABS R/H
LANDCRUISER	FZJ80	1/1990-	1FZFE Petrol	43411-60090FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub & Full Time 4wd R/H
LANDCRUISER	FZJ80	4/1994-	1FZFE Petrol	43411-60090NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub & ABS R/H
LANDCRUISER	FZJ100	1/1998-	1FZFE Petrol	43430-60040TT	CV Joint & Drive Shaft Assembly L/H & R/H
LANDCRUISER	FZJ105	1/1998-	1FZFE Petrol	43405-60110TT	CV Joint with ABS non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FZJ105	1/1998-	1FZFE Petrol	43405-60100TT	CV Joint non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FZJ105	1/1998-	1FZFE Petrol	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	FZJ105	1/1998-	1FZFE Petrol	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	FZJ105	1/1998-	1FZFE Petrol	43412-ABSCV	CV Joint & Axle Shaft Assembly with ABS non Free Wheeling Hub Type L/H
LANDCRUISER	FZJ105	1/1998-	1FZFE Petrol	43412-NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub & ABS L/H
LANDCRUISER	FZJ105	1/1998-	1FZFE Petrol	43412-60110FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub & Full Time 4wd L/H
LANDCRUISER	FZJ105	1/1998-	1FZFE Petrol	43411-ABSCV	CV Joint & Axle Shaft Assembly with ABS non Free Wheeling Hub Type R/H
LANDCRUISER	FZJ105	1/1998-	1FZFE Petrol	43411-NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub & ABS R/H
LANDCRUISER	FZJ105	1/1998-	1FZFE Petrol	43411-60090FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub & Full Time 4wd R/H
LANDCRUISER	GRJ200	9/2007-	1GRFE Petrol	43403-60030TT	CV Joint Inner L/H & R/H
LANDCRUISER	GRJ200	9/2007-	1GRFE Petrol	43430-60071TT	CV Joint & Drive Shaft Assembly L/H & R/H
LANDCRUISER	HJ45	1/1979-10/1984	H Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	HJ45	1/1979-10/1984	H Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	HJ45	1/1979-10/1984	H Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	HJ47	8/1980-10/1984	2H Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	HJ47	8/1980-10/1984	2H Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	HJ47	8/1980-10/1984	2H Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	HJ60	8/1980-1/1990	2H Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	HJ60	8/1980-1/1990	2H Diesel	43412-35010CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	HJ60	8/1980-1/1990	2H Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	HJ61	8/1980-1/1990	12HT Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	HJ61	8/1980-1/1990	12HT Diesel	43412-35010CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	HJ61	8/1980-1/1990	12HT Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	HJ75	11/1984-1/1990	2H Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	HJ75	11/1984-1/1990	2H Diesel	43412-60090CV	CV Joint & Axle Shaft Assembly without Diff Lock L/H
LANDCRUISER	HJ75	11/1984-1/1990	2H Diesel	43411-60060CV	CV Joint & Axle Shaft Assembly without Diff Lock R/H
LANDCRUISER	HJ75	1/1990-	2H Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	HDJ78	8/1999-	1HDT Diesel	43405-60100TT	CV Joint non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HDJ78	8/2001-1/2007	1HDT Diesel	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HDJ78	8/2001-1/2007	1HDT Diesel	43412-60120CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type L/H
LANDCRUISER	HDJ78	8/2001-1/2007	1HDT Diesel	43412-60120CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type L/H
LANDCRUISER	HDJ78	8/2001-1/2007	1HDT Diesel	43412-60120NFHCV	CV Joint & Axle Shaft non Free Wheeling Hub Type L/H
LANDCRUISER	HDJ78	8/2001-	1HDT Diesel	43411-60100CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type R/H
LANDCRUISER	HDJ78	8/1999-8/2016	1HDT Diesel	43411-60100CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type R/H
LANDCRUISER	HDJ78	8/2001-	1HDT Diesel	43411-60100NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub Type R/H
LANDCRUISER	HDJ78	8/2001-	1HDT Diesel	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	HDJ79	8/1999-	1HDT Diesel	43405-60100TT	CV Joint non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HDJ79	8/2001-1/2007	1HDT Diesel	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HDJ79	8/2001-	1HDT Diesel	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H

TERRAIN TAMER CV JOINTS – 2022.

MAKE	MODEL	YEAR	ENGINE	PART NO.	NOTES
LANDCRUISER	HDJ79	8/2001-1/2007	1HDT Diesel	43412-60120CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type L/H
LANDCRUISER	HDJ79	8/2001-1/2007	1HDT Diesel	43412-60120CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type L/H
LANDCRUISER	HDJ79	8/2001-1/2007	1HDT Diesel	43412-60120NFHCV	CV Joint & Axle Shaft non Free Wheeling Hub Type L/H
LANDCRUISER	HDJ79	8/2001-	1HDT Diesel	43411-60100CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type R/H
LANDCRUISER	HDJ79	8/1999-8/2016	1HDT Diesel	43411-60100CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type R/H
LANDCRUISER	HDJ79	8/2001-	1HDT Diesel	43411-60100NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub Type R/H
LANDCRUISER	HDJ80	8/1992-	1HDT Diesel	43405-60070TT	CV Joint with ABS L/H & R/H
LANDCRUISER	HDJ80	4/1994-	1HDT Diesel	43405-60080TT	CV Joint without ABS L/H & R/H
LANDCRUISER	HDJ80	1/1990-3/1994	1HDT Diesel	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HDJ80	1/1990-3/1994	1HDT Diesel	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	HDJ80	8/1992-	1HDT Diesel	43412-60110ABSCV	CV Joint & Axle Shaft Assembly with ABS L/H
LANDCRUISER	HDJ80	1/1990-3/1994	1HDT Diesel	43412-60110FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub & Full Time 4wd L/H
LANDCRUISER	HDJ80	4/1994-	1HDT Diesel	43412-60110NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub & ABS L/H
LANDCRUISER	HDJ80	8/1992-	1HDT Diesel	43411-60090ABSCV	CV Joint & Axle Shaft Assembly with ABS R/H
LANDCRUISER	HDJ80	1/1990-3/1994	1HDT Diesel	43411-60090FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub & Full Time 4wd R/H
LANDCRUISER	HDJ80	4/1994-	1HDT Diesel	43411-60090NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub & ABS R/H
LANDCRUISER	HDJ100	1/1998-	1HDT Diesel	43430-60040TT	CV Joint & Drive Shaft Assembly L/H & R/H
LANDCRUISER	HZJ70	1/1990-	1HZ Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	HZJ70	1/1990-	1HZ Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	HZJ70	1/1990-	1HZ Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	HZJ71	8/1999-	1HZ Diesel	43405-60100TT	CV Joint non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HZJ71	8/1999-	1HZ Diesel	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HZJ71	8/1999-	1HZ Diesel	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	HZJ71	8/1999-1/2007	1HZ Diesel	43412-60120CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type L/H
LANDCRUISER	HZJ71	8/1999-1/2007	1HZ Diesel	43412-60120CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type L/H
LANDCRUISER	HZJ71	8/1999-1/2007	1HZ Diesel	43412-60120NFHCV	CV Joint & Axle Shaft non Free Wheeling Hub Type L/H
LANDCRUISER	HZJ71	8/1999-	1HZ Diesel	43411-60100CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type R/H
LANDCRUISER	HZJ71	8/1999-8/2016	1HZ Diesel	43411-60100CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type R/H
LANDCRUISER	HZJ71	8/1999-	1HZ Diesel	43411-60100NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub Type R/H
LANDCRUISER	HZJ73	1/1990-	1HZ Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	HZJ73	1/1990-	1HZ Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	HZJ73	1/1990-	1HZ Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	HZJ75	1/1990-	1HZ Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	HZJ75	1/1990-	1HZ Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	HZJ75	1/1990-	1HZ Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	HZJ76	1/2007-	1HZ Diesel	43405-60100TT	CV Joint non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HZJ76	1/2007-	1HZ Diesel	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HZJ76	1/2007-	1HZ Diesel	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	HZJ76	1/2007-	1HZ Diesel	43412-60120NFHCV	CV Joint & Axle Shaft non Free Wheeling Hub Type L/H
LANDCRUISER	HZJ76	1/2007-	1HZ Diesel	43412-60140CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type L/H
LANDCRUISER	HZJ76	1/2007-	1HZ Diesel	43412-60140TTCVG	CV Joint & Axle Shaft Assembly with Grease Valve Auto & Free Wheeling Hub Type L/H
LANDCRUISER	HZJ76	1/2007-	1HZ Diesel	43411-60100CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type R/H
LANDCRUISER	HZJ76	8/1999-8/2016	1HZ Diesel	43411-60100CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type R/H
LANDCRUISER	HZJ76	1/2007-	1HZ Diesel	43411-60100NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub Type R/H
LANDCRUISER	HZJ77	1/1990-	1HZ Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	HZJ77	1/1990-	1HZ Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	HZJ77	1/1990-	1HZ Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	HZJ78	8/1999-	1HZ Diesel	43405-60100TT	CV Joint non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HZJ78	8/1999-	1HZ Diesel	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H

TERRAIN TAMER CV JOINTS – 2022.

MAKE	MODEL	YEAR	ENGINE	PART NO.	NOTES
LANDCRUISER	HZJ80	1/1990-	1HZ Diesel	43412-60110FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub & Full Time 4wd L/H
LANDCRUISER	HZJ80	4/1994-	1HZ Diesel	43412-60110NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub & ABS L/H
LANDCRUISER	HZJ80	8/1992-	1HZ Diesel	43411-60090ABSCV	CV Joint & Axle Shaft Assembly with ABS R/H
LANDCRUISER	HZJ80	1/1990-	1HZ Diesel	43411-60090FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub & Full Time 4wd R/H
LANDCRUISER	HZJ80	4/1994-	1HZ Diesel	43411-60090NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub & ABS R/H
LANDCRUISER	HZJ105	1/1998-	1HZ Diesel	43405-60110TT	CV Joint with ABS non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HZJ105	1/1998-	1HZ Diesel	43405-60100TT	CV Joint non Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HZJ105	1/1998-	1HZ Diesel	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	HZJ105	1/1998-	1HZ Diesel	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	HZJ105	1/1998-	1HZ Diesel	43412-ABSCV	CV Joint & Axle Shaft Assembly with ABS non Free Wheeling Hub Type L/H
LANDCRUISER	HZJ105	1/1998-	1HZ Diesel	43412-NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub & ABS L/H
LANDCRUISER	HZJ105	1/1998-	1HZ Diesel	43412-60110FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub & Full Time 4wd L/H
LANDCRUISER	HZJ105	1/1998-	1HZ Diesel	43411-ABSCV	CV Joint & Axle Shaft Assembly with ABS non Free Wheeling Hub Type R/H
LANDCRUISER	HZJ105	1/1998-	1HZ Diesel	43411-NFHCV	CV Joint & Axle Shaft Assembly non Free Wheeling Hub & ABS R/H
LANDCRUISER	HZJ105	1/1998-	1HZ Diesel	43411-60090FHCV	CV Joint & Axle Shaft Assembly suits Free Wheeling Hub & Full Time 4wd R/H
LANDCRUISER	LJ70	11/1984-1/1990	2LT Diesel	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	LJ70	1/1990-	2LT Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	LJ70	1/1990-	2LT Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	LJ70	1/1990-	2LT Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	LJ72	4/1990-3/1996	3L Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	LJ72	4/1990-3/1996	3L Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	LJ72	4/1990-3/1996	3L Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	LJ77	4/1990-4/1993	2LT Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	LJ77	4/1990-4/1993	2LT Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	LJ77	4/1990-4/1993	2LT Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	LJ79	4/1990-3/1996	3L Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	LJ79	4/1990-3/1996	3L Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	LJ79	4/1990-3/1996	3L Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	PZJ70	1/1990-	1PZ Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	PZJ70	1/1990-	1PZ Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	PZJ70	1/1990-	1PZ Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	PZJ73	1/1990-	1PZ Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	PZJ73	1/1990-	1PZ Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	PZJ73	1/1990-	1PZ Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	PZJ75	1/1990-	1PZ Diesel	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	PZJ75	1/1990-	1PZ Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	PZJ75	1/1990-	1PZ Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	RJ70	11/1984-1/1990	22R Petrol	43405-60015TT	CV Joint L/H & R/H
LANDCRUISER	RJ70	1/1990-	22R Petrol	43405-60040TT	CV Joint L/H & R/H
LANDCRUISER	RJ70	1/1990-	22R Petrol	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
LANDCRUISER	RJ70	1/1990-	22R Petrol	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
LANDCRUISER	UZJ100	1/1998-	2UZFE Petrol	43430-60040TT	CV Joint & Drive Shaft Assembly L/H & R/H
LANDCRUISER	URJ200	9/2007-	3URFE Petrol	43403-60030TT	CV Joint Inner L/H & R/H
LANDCRUISER	URJ200	9/2007-	3URFE Petrol	43430-60071TT	CV Joint & Drive Shaft Assembly L/H & R/H
LANDCRUISER	UZJ200	9/2007-	2UZFE Petrol	43403-60030TT	CV Joint Inner L/H & R/H
LANDCRUISER	UZJ200	9/2007-	2UZFE Petrol	43430-60071TT	CV Joint & Drive Shaft Assembly L/H & R/H
LANDCRUISER	VDJ76	1/2007-	1VDFTV Diesel	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	VDJ76	1/2007-	1VDFTV Diesel	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	VDJ76	1/2007-	1VDFTV Diesel	43412-60140CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type L/H
LANDCRUISER	VDJ76	1/2007-	1VDFTV Diesel	43412-60140TTCVG	CV Joint & Axle Shaft Assembly with Grease Valve Auto & Free Wheeling Hub Type L/H
LANDCRUISER	VDJ76	1/2007-	1VDFTV Diesel	43411-60100CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type R/H
LANDCRUISER	VDJ76	8/1999-8/2016	1VDFTV Diesel	43411-60100CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type R/H
LANDCRUISER	VDJ78	1/2007-	1VDFTV Diesel	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	VDJ78	1/2007-	1VDFTV Diesel	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	VDJ78	1/2007-	1VDFTV Diesel	43412-60140CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type L/H
LANDCRUISER	VDJ78	1/2007-	1VDFTV Diesel	43412-60140TTCVG	CV Joint & Axle Shaft Assembly with Grease Valve Auto & Free Wheeling Hub Type L/H
LANDCRUISER	VDJ78	1/2007-	1VDFTV Diesel	43411-60100CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type R/H
LANDCRUISER	VDJ78	8/1999-8/2016	1VDFTV Diesel	43411-60100CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type R/H
LANDCRUISER	VDJ79	1/2007-	1VDFTV Diesel	43405-60120TT	CV Joint Free Wheeling Hub Type L/H & R/H
LANDCRUISER	VDJ79	1/2007-	1VDFTV Diesel	43405-60120TTG	CV Joint Auto & Free Wheeling Hub Type with Grease Valve L/H & R/H
LANDCRUISER	VDJ79	1/2007-	1VDFTV Diesel	43412-60140CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type L/H
LANDCRUISER	VDJ79	1/2007-	1VDFTV Diesel	43412-60140TTCVG	CV Joint & Axle Shaft Assembly with Grease Valve Auto & Free Wheeling Hub Type L/H
LANDCRUISER	VDJ79	1/2007-	1VDFTV Diesel	43411-60100CV	CV Joint & Axle Shaft Assembly Free Wheeling Hub Type R/H
LANDCRUISER	VDJ79	8/1999-8/2016	1VDFTV Diesel	43411-60100CVG	CV Joint & Axle Shaft Assembly with Grease Valve Free Wheeling Hub Type R/H
LANDCRUISER	VDJ200	9/2007-	1VDFTV Diesel	43403-60030TT	CV Joint Inner L/H & R/H
LANDCRUISER	VDJ200	9/2007-	1VDFTV Diesel	43430-60071TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	GDJ150	6/2015-	1GDFTV Diesel	43430-60060TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	GRJ120	9/2002-	1GRFE Petrol	43430-60060TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	KDJ120	9/2002-	1KDFTV Diesel	43430-60060TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	KZJ70	5/1993-3/1996	1KZT Diesel	43405-60040TT	CV Joint L/H & R/H
PRADO	KZJ70	5/1993-3/1996	1KZT Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
PRADO	KZJ70	5/1993-3/1996	1KZT Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H

TERRAIN TAMER CV JOINTS – 2022.

MAKE	MODEL	YEAR	ENGINE	PART NO.	NOTES
PRADO	KZJ73	5/1993-3/1996	1KZT Diesel	43405-60040TT	CV Joint L/H & R/H
PRADO	KZJ73	5/1993-3/1996	1KZT Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
PRADO	KZJ73	5/1993-3/1996	1KZT Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
PRADO	KZJ77	5/1993-3/1996	1KZT Diesel	43405-60040TT	CV Joint L/H & R/H
PRADO	KZJ77	5/1993-3/1996	1KZT Diesel	43412-60100CV	CV Joint & Axle Shaft Assembly L/H
PRADO	KZJ77	5/1993-3/1996	1KZT Diesel	43411-60070CV	CV Joint & Axle Shaft Assembly R/H
PRADO	KZJ90	4/1996-	1KZTE Diesel	43430-35030TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	KZJ95	4/1996-	1KZTE Diesel	43430-35030TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	KZJ120	9/2002-	1KZTE Diesel	43430-60060TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	RZJ90	4/1996-	3RZFE Petrol	43430-35030TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	RZJ95	4/1996-	3RZFE Petrol	43430-35030TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	RZJ120	9/2002-	3RZFE Petrol	43430-60060TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	VZJ90	4/1996-	5VZFE Petrol	43430-35030TT	CV Joint & Drive Shaft Assembly L/H & R/H
PRADO	VZJ95	4/1996-	5VZFE Petrol	43430-35030TT	CV Joint & Drive Shaft Assembly L/H & R/H
TACOMA	GRN245	9/2004-	1GRFE Petrol	43430-60060TT	CV Joint & Drive Shaft Assembly L/H & R/H
TACOMA	GRN250	9/2004-	1GRFE Petrol	43430-60060TT	CV Joint & Drive Shaft Assembly L/H & R/H
TACOMA	TRN240	9/2011-7/2014	2TRFE Petrol	43430-60060TT	CV Joint & Drive Shaft Assembly L/H & R/H
TACOMA	TRN245	9/2011-7/2014	2TRFE Petrol	43430-60060TT	CV Joint & Drive Shaft Assembly L/H & R/H

